


PLAN



ELEVATION

NOTES

- 1. REPAIRS SHALL BE MADE IN ACCORDANCE WITH SECTION 522 OF THE SPECIFICATIONS.
- 2. REPAIRS SHALL BE MADE USING CONCRETE MEETING THE REQUIREMENTS OF SECTION 522.02 OF THE SPECIFICATIONS.
- 3. SUBGRADE PREPARATION SHALL BE MADE IN ACCORDANCE WITH SUBSECTION 522.03.04 OF THE SPECIFICATIONS.
- 4. LONGITUDINAL JOINT SHALL BE MADE IN ACCORDANCE WITH SECTION 520 OF THE SPECIFICATIONS AND STD. MD 577.07.
- 5. ALL REINFORCEMENT BARS, CHAIRS, TIE DEVICES AND TIE WIRES SHALL BE EPOXY COATED.
- 6. PAVEMENT REPAIR SAW CUTS AND LIFT OUT METHOD SEE STD. MD 577.01.
- 7. REINFORCEMENT STEEL OVERLAP SHALL BE 18" MINIMUM FOR NO.5 STEEL BARS AND 22" MINIMUM FOR NO. 6 STEEL BARS.
- 8. IN INSTANCES WHERE THE EXISTING PAVEMENT WAS POURED AS ONE SLAB THE LONGITUDINAL TIE DEVICES ARE NOT APPLICABLE. THE SAW CUTS SHALL EXTEND THE FULL WIDTH OF THE PAVEMENT.

